USEPA 290 BROADWAY NY, NY

NOTIFICATION OF DEMOLITION AND RENOVATION PAL JOB # 21-1109

Operator Project #	Postmark	Date R		Received		Notific	Notification #	
TYPE OF NOTIFICATION (O-Original, R-Received, C-Cancelled): R — New Start Date, Change Waste Hauler Information & Add								
Material								
FACILITY INFORMATION (Ide	ntify Owner, R	Removal Contra	ctor and C	Other Opera	tor):			
OWNER NAME: American Airli	nes			•				
Address: JFK Airport								
City: Jamaica				State: NY			Zip: 11430	
Contact Name: David Richards	S			Telephone: 7			one: 718-487-6726	
REMOVAL CONTRACTOR: PAL	. Environmenta	al Safety Corp.	d/b/a PAL	Environme	ntal Services			
Address: 11-02 Queens Plaza	South							
City: Long Island City				State: NY			Zip: 11101	
Contact Name: Aric Domozick		Telephone: 718-349-0900				one: 718-349-0900		
OTHER CONTRACTOR:								
Address:								
City:				State:			Zip:	
Contact Name:				Telephone:				
TYPE OF OPERATION (D-Dem		Demo, R-Reno	vation, E-	Emergency	Renovation: R			
IS ASBESTOS PRESENT? (YES	NO) YES							
FACILITY DESCRIPTION (Include Building Name, Number and Floor or Room Number)								
Building Name: JFK Airport								
Address: American Airlines Te	erminal 8							
City: Jamaica				State: NY			Zip: 11430	
Site Location: Terminal 8								
Building Size: F				# of Floors:			Age in Years:	
Present Use: Airport				Prior Use: Airport				
Procedure, Including Analytica	al Method, If A	ppropriate, Use 1 – Polarized Li	ed to Dete	ct the Prese	ence of Asbesto	os Material:		
	PLI	1 – Polatizeu Li	gnt Micros	сору				
Approximate amount of asbes	tos	R. ACM		Non-l	Friable	Indic	ate Unit	of Measurement
Including	,	to be		Asbestos Material		Below		
Regulated ACM to be rem	noved	removed		not to be removed				
Category I ACM not remo								
3. Category II ACM not rem				CAT I	CAT II			UNIT
				0,11,1	<i>G</i> ,		`	51411
Surface Area:						Linear Fee	t:	Ln M:
Surface Area: Tar Wrap		460				Square Fe	et: X	Square Meter:
Volume RACM off Facility Com						Cu Ft:		Cu M:
Scheduled Dates Asbestos Removal (mm/dd./yy)			S	Start: 09/13/2021		Complete: 09/01/2022		
Scheduled Dates Demo/Renovation (mm/dd./yy)			S	Start:		Complete:		

SCRIPTION OF PLANNED DEMOLITION OR	RENOVATION WORK, AND METHO	DD (S) TO BE USED:					
ESCRIPTION OF WORK PRACTICES AND FIN	SINEERING CONTROLS TO BE USE	D TO PREVENT EMISSIONS OF ASBESTOS AT					
THE DEMOLITION AND RENOVATION SITE:	5111211110 00111110120 10 52 052						
HEPA Vacs, Micro Traps (Negative Air Pressure	e) and amended water will be utiliz	ed for emissions control.					
WASTE TRANSPORTER #1							
Name: Rizzo Environmental Services Corp.							
Address: 5700 47th Street							
City: Maspeth	State: NY	Zip: 11378					
Contact Name: Raymond J. Rizzo	1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Telephone: 516-791-9000					
WASTE TRANSPORTER #2							
Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services							
Address: 11-02 Queens Plaza South							
City: Long Island	State: NY	Zip: 11101					
Contact Name: Aric Domozick		Telephone: 718-349-0900					
WASTE TRANSPORTER #3							
Name:							
Location:		T =-					
City:	State:	Zip:					
Telephone:							
Disposal Facility							
Name: 110 Sand Clean Fill Disposal Site	-						
Location: 136 Bethpage - Spagnoli Road		Zip: 11747					
City: Melville	State: NY	Zip: 11747					
FOR EMERGENCY RENOVATIONS							
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy)							
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event	;	nt damage or an unreasonable financial burden:					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe	conditions or would cause equipmen	nt damage or an unreasonable financial burden:					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO	conditions or would cause equipmer WED IN THE EVENT THAT UNEXPE	CTED ASBESTOS IS FOUND OR PREVIOUSLY					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NOMERIABLE ASSESTOS MATERIAL BECOME:	conditions or would cause equipmer WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes to be put in 6 mil poly bags for proper	conditions or would cause equipmer WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED omes crumbled, will be immediately disposal.	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper	conditions or would cause equipment WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED Dimes crumbled, will be immediately disposal. NITHE PROVISIONS OF THIS REGUL	UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II STEP DURING THE DEMOLITION OR RENOVA	conditions or would cause equipment WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED OTHER COMMENTARY DISTRIBUTION STATE PROVISIONS OF THIS REGUA STION AND EVIDENCE THAT THE RE	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II STEP DURING THE DEMOLITION OR RENOVA	conditions or would cause equipment WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED OTHER COMMENTARY DISTRIBUTION STATE PROVISIONS OF THIS REGUA STION AND EVIDENCE THAT THE RE	UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II STEP DURING THE DEMOLITION OR RENOVA	conditions or would cause equipment WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED TO THE REMONIANT OF THIS REGU THE PROVISIONS OF THIS REGU TO THE PROVISIONS OF THAT THE RESTRICT OF THE RESTRICT OF THE RESTRICT OF THE RESTRICT OF THE RESTRICT ON DURING NORMAL BUSINES	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II SITE DURING THE DEMOLITION OR RENOVATHIS PERSON WITH BE AVAILABLE FOR INSE	conditions or would cause equipment WED IN THE EVENT THAT UNEXPE S CRUMBLED, PULVERIZED OR RED OTHER STANDARD OTHER STANDARD OTHER PROVISIONS OF THIS REGUN OTHER PROVISIONS OF THAT THE RESTORM OF THE R	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II SITE DURING THE DEMOLITION OR RENOVATHIS PERSON WITH BE AVAILABLE FOR INSE	conditions or would cause equipment wed in the event that unexpersions of crumbled, pulverized or recommendately disposal. No the provisions of this regulation and evidence that the recommendately disposal. ECTION DURING NORMAL BUSINES 09/09/2021 Date	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes Vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II SITE DURING THE DEMOLITION OR RENOVATHIS PERSON WITH BE AVAILABLE FOR INSE	conditions or would cause equipment wed in the event that unexpersions of crumbled, pulverized or recommendately disposal. No the provisions of this regulation and evidence that the recommendately disposal. ECTION DURING NORMAL BUSINES 09/09/2021 Date	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which becomes vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II SITE DURING THE DEMOLITION OR RENOVATHIS PERSON WITH BE AVAILABLE FOR INSE	conditions or would cause equipment wed in the event that unexpersions of crumbled, pulverized or recommendately disposal. No the provisions of this regulation and evidence that the recommendately disposal. ECTION DURING NORMAL BUSINES 09/09/2021 Date	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					
FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event Explanation of how the event caused unsafe DESCRIPTION OF PROCEDURE TO BE FOLLO NONFRIABLE ASBESTOS MATERIAL BECOME: unexpectedly, or non-friable ACM, which become vacs, to be put in 6 mil poly bags for proper I CERTIFY THAT AN INDIVIDUAL TRAINED II SITE DURING THE DEMOLITION OR RENOVATHIS PERSON WITH BE AVAILABLE FOR INSERTING THE DEMOLITION OF RENOVATION OF THE DEMOLITION OF RENOVATION OF THE DEMOLITION OF THE DEMOLIT	conditions or would cause equipment WED IN THE EVENT THAT UNEXPES CRUMBLED, PULVERIZED OR RED of the comment of	CTED ASBESTOS IS FOUND OR PREVIOUSLY UCED TO POWDER. Any ACM, which is discovered wet with amended water and cleaned up with HEPA ALTION (40 CFT PART 61, SUBPART M), WILL BE ON-					